



Original Tree Position	Site	Original Tree Species	Confirm Reason for Removal	6 D's	Original Tree Easting	Original Tree Northing	Planting Notes	Replant Species	Replant Easting	Replant Northing
o/s 35	SHELDON ROAD	Platanus x hispanica	Damage to Surface	Damaging	434331.05	384826.26	TR: Replanting, Tilia 'Rancho' - Plant in new 800mm pit o/s between 33-35 (same as felled tree)	Tilia cordata 'Rancho'	434332.89	384824.88
o/s 53	SHELDON ROAD	Acer pseudoplatanus	Carriageway Obstruction	Discriminatory	434388.25	384804.65	TR: Replanting, Tilia 'Rancho' - Plant in new 800mm pit o/s between 53-55 (same as felled tree)	Tilia cordata 'Rancho'	434388.76	384804.56
o/s 44	SHELDON ROAD	Platanus x hispanica	Damage to Surface	Damaging	434385.88	384796.43	TR: Replanting, Tilia 'Rancho' - Plant in new 800mm pit o/s 45, (relocated across road to accomodate streetlighting design)	Tilia cordata 'Rancho'	434362.08	384810.8

o/s 60	SHELDON ROAD	Platanus x hispanica	Damage to Surface	Damaging	434451.89	384779.23	TR: Replanting, Tilia 'Rancho' - Plant in new 800mm pit o/s 60 (same as felled tree)	Tilia cordata 'Rancho'	434451.57	384779.54
o/s 32 to 34	SHELDON ROAD	Platanus x hispanica	Damage to Surface	Damaging	434353.08	384806.6	TR: Replanting, Tilia 'Rancho' - Plant in new 800mm pit o/s 41 (opposite felled tree, moved across road to accomodate streetlighting design)	Tilia cordata 'Rancho'	434353.17	384814.41
o/s 28	SHELDON ROAD	Platanus x hispanica	Carriageway Obstruction	Discriminatory	434336.9	384814.22	TR: Replanting, Tilia 'Rancho' - Plant in new 800mm pit o/s 28 (same as felled tree)	Tilia cordata 'Rancho'	434336.95	384814.11
o/s 26	SHELDON ROAD	Acer pseudoplatanus	Damage to Surface	Damaging	434327.91	384818.72	TR: Replanting, Tilia 'Rancho' - Plant in new 800mm pit o/s 26 (same as felled tree)	Tilia cordata 'Rancho'	434336.95	384814.11

o/s 22	SHELDON ROAD	Acer pseudoplatanus	Damage to Surface	Damaging	434321.13	384821.77	TR: Replanting, Tilia 'Rancho' - Plant in new 800mm pit o/s 22 (same as felled tree)	Tilia cordata 'Rancho'	434320.79	384821.7
o/s 85	SHELDON ROAD	Platanus x hispanica	Damage to Structures	Damaging	434533	384766.01	TR: Replanting - Corylus columna - o/s 83-85 (new pit) - NB there is currently a 'Bus Lane' sign at this location, IHOR has spoken with N. Marriott who agrees the sign can be relocated.	Corylus columna	434530.35	384767.29
o/s 14	SHELDON ROAD	Acer pseudoplatanus	Damage to Surface	Damaging	434295.86	384833.63	TR: Replanting, Tilia 'Rancho' - Plant in new 800mm pit centrally o/s 14 (same as felled tree)	Tilia cordata 'Rancho'	434293.31	384834.23